



Software Version: 1.07.01
Agent Version: V3.6.7-b04
Published Date: 2021/9/7

Content:

Revision History 2

System Requirements (Minimum HW Requirements) 2

New Features 2

Enhancements 3

Problems Fixed..... 4

Known Issues 4

Related Documentation 4

Revision History

Software Version	Agent Version	Date	Model	Hardware Version
1.00.06	3.4.9-b02	2020/05/31	DCS-8302LH	A1
1.01.03	3.5.3-b01	2020/08/17	DCS-8302LH	A1
1.02.01	3.5.11-b07	2020/12/2	DCS-8302LH	A1
1.03.02	3.5.16-b05	2021/01/27	DCS-8302LH	A1
1.04.05	3.5.18-04	2021/04/08	DCS-8302LH	A1
1.05.01	3.6.2-b04	2021/05/24	DCS-8302LH	A1
1.06.02	3.6.2-b04	2021/07/14	DCS-8302LH	A1
1.07.01	3.6.7-b04	2021/09/07	DCS-8302LH	A1

System Requirements (Minimum HW Requirements)

System Minimum Requirements	
System Requirements	mydlink APP for iPhone, iPad, Android phone and tablet.
Network Requirements	At least 1.5Mbps upload bandwidth per camera.
App Requirements	Compatible with iPhone and iPad using iOS 11 or higher Compatible with Android smartphones and tablets using Android 5.0 or higher

New Features

Software Version	New Features
1.01.03	1. Add LED status solid green when managed by ONVIF 2. Add LED status solid orange when enable privacy mode
1.02.01	NA
1.03.02	1. Supports BLE auto-off 2. Supports 720P/1080P resolution switching
1.04.05	NA
1.05.01	1. Supports Continuous Recording 2. Fixed ONVIF set camera streaming bitrate failure.
1.06.02	NA
1.07.01	NA

Enhancements

Firmware Version	Problems Fixed
1.01.03	1. Time will sync with NTP server when the camera is added to NVR 2. Enhanced night vision image quality 3. Enhanced Wi-Fi re-connection time 4. Reduced Audio Input Noise Level
1.02.01	1. Update the Day/Night mode switch logic 2. Enhance Person Detection sensitivity 3. Support multilingual SSID
1.03.02	1.Supports ONVIF protocol once the Camera gets an IP address 2.Enhance the RTSP streaming stability when played in VLC 3.Enhance playback audio and video sync
1.04.05	1. Supports Image Invert Function.
1.05.01	NA
1.06.02	1. Update the Wi-Fi driver to fix security issue.
1.07.01	NA

Problems Fixed

Software Version	Problems Fixed
1.01.03	- Fixed issue where recorded video is too short or cannot be found - Fixed OSD and Logo Sizing
1.02.01	- Fixed incorrect ONVIF scope name - Fixed DUT will not re-connect with Synology NAS - Fixed playback will show “video lost” issue - Fixed DUT occasionally detects false SD card fault - Fixed DUT will not stream live video after disabling privacy mode. - Fixed sporadic SD card format failures - Fixed multilingual SSID display issue
1.03.02	- Fixed playback of recorded video shows date of 2000/01/01 after device reboot - Fixed the Abnormal LED Status after binding with ethernet connection
1.04.05	Fixed issue where day/night mode switching continues even when privacy mode is activated.
1.05.01	- Fixed issue where DNH-200 cannot modify the camera name. - Fixed ONVIF set camera streaming bitrate failure.
1.06.02	NA
1.07.01	Fixed ONVIF probe message ID issue.

Known Issues

Firmware Version	Known Issues

Related Documentation

N/A