

DIR-505 Revision A Release Notes

=====
Firmware 1.08
Date: 05/19/2014

Release notes
Fixed buffer flow security issue

=====
DIR-505 Revision A Release Notes

=====
Firmware 1.07
Date: 09/05/2013

Release notes
Fixed security vulnerabilities

=====
Firmware 1.06
Date:

Release Notes:
- Fixed DUT issue at repeat/hotspot mode
- Fixed DUT issue of WPS function when MAC address filter is enabled

=====
Firmware 1.05
Date: 10/29/2012

Revision Info:
Fixed: Enhance iOS 6 Compatibility.

=====
Firmware 1.04
Date: 09/26/2012

Revision Info:
Fixed: Setup wizard issue.
Fixed: USB storage issue.
Fixed: IP renew issue for Repeater mode.
Fixed: WPS LED issue:
Fixed: Wireless site survey issue.
Fixed: Wi-Fi connection issue for Repeater and WiFi Hotspot mode.
Fixed: WPS-PBC issue.
Fixed: large file transfer issue.
Support https://shareport and https://shareport.local
Support IP conflict detection.

=====
Firmware 1.03
Date: 07/11/2012

Revision Info:
Fixed: LED Issue.
Fixed: Log file name issue for SharePort Web Access.

=====
Firmware 1.02
Date: 06/04/2012

Revision Info:
Fixed: MAC Address issue.
Fixed: USB storage issue.
Fixed: Web File Access log in issue.
Fixed: Web File Access display issue.

=====
Firmware 1.01
Date: 05/04/2012

Revision Info:
DHCP Client MAC Address issue.
MAC Address display issue.

=====