

DIR-600L Firmware Patch Notes

Firmware: FW2.07.B01WW Hardware: B1 Date: 2015/05/07

Note: None

Problems Resolved:

- Fixed Security vulnerabilities as described on [SAP10055]
 - Authentication Bypass
 - Remote Code Execution

For details visit: http://securityadvisories.dlink.com/security/publication.aspx?name=SAP10055

Enhancements: None

Known Issues: None