



DIR-615 Firmware Release Notes

Firmware: FW v514b04

Hardware: Rev.E4

Date: 2014/04/14

Note:

- FW version is advanced to v5.14

Problems Resolved:

- Fixed the exploit in "<http://192.168.0.1/apply.cgi>" that can be used for CSRF attack from LAN side.

Enhancements:

None

Known Issues:

None
