



## **DIR-615 Firmware Patch Notes**

**Firmware:** FW10.02.B01

**Hardware:** J1

**Date:** 2015/05/12

**Note:**

None

**Problems Resolved:**

- **Fixed Security vulnerabilities as described on [\[SAP10055\]](#)**
  - Authentication Bypass
  - Remote Code Execution

**For details visit:**

<http://securityadvisories.dlink.com/security/publication.aspx?name=SAP10055>

**Enhancements:**

None

**Known Issues:**

None

---