



DIR-866L Firmware Release Notes

Firmware: FW v1.03B04

Hardware: Rev.A1

Date: 2015/11/06

Problems Resolved:

1. Fixed typo in mydlink UI.
2. Fixed Buffer Overflow issue.
3. Fixed authorization issue in login stage.
4. Fixed iOS QRS configuration issue..
5. Fixed wizard configuration failure through WLAN interface.

Enhancements:

Note:

N/A

----- END -----
