



Firmware Version: V2.03.00
Published Date: 2016/07/21

Content:

New Features: 2

Problems Fixed: 3

Known Issues: 4

Related Documentation: 4

Revision History and System Requirement:

Software Version	Date	Model	Hardware Version
V2.00.05	2015/02/03	DNR-202L	A1
V2.00.06	2015/03/07	DNR-202L	A1
V2.01.01	2015/06/10	DNR-202L	A1
V2.01.02	2015/06/10	DNR-202L	A1
V2.01.03	2015/07/06	DNR-202L	A1
V2.01.04	2015/08/14	DNR-202L	A1
V2.02.00	2015/09/17	DNR-202L	A1
V2.03.00	2016/07/19	DNR-202L	A1

System Requirement (minimum HW requirement)

System Minimum Requirements	
Hardware Requirements	Two USB hard disk drive
Network Requirements	Broadband Internet connection (for remote access) Network camera(s) (refer to the D-Link website for a list of supported cameras) 10/100/1000 Mbit Ethernet switch or router
Web-based Configuration Utility Requirements/Remote PC Minimum Requirements	Computer with the following: Computer with Microsoft Windows 7, 8, Vista, or XP (with Service Pack 3); Mac OS X (10.7 or above) PC with Pentium 4 – 2.4 GHz or above; at least 512MB RAM Internet Explorer 8, Firefox 12, Chrome 20, or Safari 4 or higher. Existing 10/100/1000 Ethernet-based network

New Features:

Fireware Version	New Features
V2.00.05	New Model MP
V2.00.06	N/A
V2.01.01	1. Add Skip function in the Setup HDD for NVR page.

	2. Add Set time zone function.
V2.01.02	N/A
V2.01.03	N/A
V2.01.04	N/A
V2.02.00	N/A
V2.03.00	N/A

Enhancements:

Firmware Version	Problems Fixed
V2.00.05	N/A
V2.00.06	1. mydlink registration information is transmitted encrypted using https protocol.
V2.01.01	N/A
V2.01.02	N/A
V2.01.03	N/A
V2.01.04	N/A
V2.02.00	N/A
V2.03.00	1. "+" is available for creating an mydlink account.

Problems Fixed:

Firmware Version	Problems Fixed
V2.00.05	N/A
V2.00.06	N/A
V2.01.01	N/A
V2.01.02	1. Fixed the UI abnormal on Russia language.
V2.01.03	1. Fixed the UI abnormal on Russia language.

V2.01.04	1. Fixed DBG15070106—Wizard couldn't search DUT to setup.
V2.02.00	1. Remove link bar.
V2.03.00	1. Fixed D-track HQ20160715000003: DNR-202L Setup Wizard does not work with Mac OS X Lion v10.7.5.

Known Issues:

Firmware Version	Known Issues
V2.00.05	N/A
V2.00.06	N/A
V2.01.01	N/A
V2.01.02	N/A
V2.01.03	N/A
V2.01.04	N/A
V2.02.00	N/A
V2.03.00	N/A

Related Documentation:

N/A