



Firmware Version: V03.01.4800.01 Prom Code Version: Published Date: 2012/7/11

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	3
Known Issues:	4
Related Documentation:	4





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V03.00.4800.28	2011/9/22	DNS-1550-04	A1
V03.00.4800.33 & Sharecenter NAVI 1.9.4800.5 (for windows) and 1.9.4800.3(for MAC)	2012/4/17	DNS-1550-04 DNS-1250-04 DNS-1250-06	DNS-1550-04 rev. A1 and A2 DNS-1250-04 A1 DNS-1250-06 A1
V03.01.4800.01	2012/7/11	DNS-1550-04 DNS-1250-04 DNS-1250-06	DNS-1550-04 rev. A1 and A2 DNS-1250-04 A1 DNS-1250-06 A1

Upgrading Instructions:

N/A. please follows procedures in user manual

New Features:

Fireware Version	New Features
V03.00.4800.28	Initial Release for DNS-1550-04
V03.00.4800.28	Initial Release for DNS-1250-04/ DNS-1250-06.
	[New Features]
	1. Add Dropbox backup
	2. Batch user creation
	3. User import/export
	4. Add Microsoft DFS
	5. Add Apple Time machine backup
	6. Add NAS replication to iSCSI (restore from iSCSI)
	7. Add iSCSI boot
	8. Add Automatic Acoustic Management in physical drive
V03.00.4800.01	9. Add DMC in DLNA package
V03.00.4800.01	10. Add SMS support
	[Enhancement]
	1. AD domain permission save/restore
	2. Open Amazon S3 and Dropbox to user mode.
	3. Support SFTP (SSH)
	4. Support multiple printers
	5. Add backup policy in remote backup (add/sync/copy)
	6. Support VessRAID remote backup (VessRAID auto-list)
	7. Dashboard enhancement
	- Firmware download directly in dashboard



Add backup status dashboard
Add file system status
Add CPU/memory usage
8. Event log
Add event filter
Send alert mail by level settings.
9. Add user monitor
10. Support remote OPAS
11. Add soft-quota control
12. Add operating log system
13. Add self-diagnostic
14. Support upgrade FW without drives

Problems Fixed:

Firmware Version	Problems Fixed
V03.00.4800.28	N/A
	1. RB-200325: FW_SFTP can login DNS-1250/ 1550 and see all data in NAS.
	 RB-200765: MacOS 10.7 can't access DNS-1250/ 1550 AFP function.
	3. RB-200907: "successful"wording issue on iSCSI PING
	4. RB-200908: "Alias must contain only alphanumeric characters, blank
	spaces and underscores." Issue
	5. RB-200911: "Enable Power Management" in disk array settings could
	not checked
	6. RB-200913: "disconnect" wording issue while setting up the
V03.00.4800.29	message alert
(Non-release version)	7. RB-200914: .adlocks folder and .backupcfg file need to be hidden
versiony	from FileZilla
	8. RB-200915: AD group could change AD members in wizards but
	could not be saved
	9. RB-200916: User name could not be more than 16 characters
	10. RB-200917: While NAS unit joined AD, can't create any local accour
	11. RB-200925: Test E-mail alert shows no messages for the user if it
	successful or not
	12. RB-200970: EVT:LUM Mapping can not be setting , when just one
	initiator
	13. RB-200971: EVT: The firmware upgrade page will hyperplasia , when
reen	



	click this page during deleting filesystem
	14. RB-200973: EVT: The typesetting of LD should be more smoothly
	15. RB-200975: EVT: The typesetting of FW upgrade should be more smoothly
	16. RB-200982: FTP setting fails
	17. RB-200990: E-mail alert with SMTP Authentication function does not work with Gmail
	18. RB-201008: [FW] Can't support Windows 2008 R2 AD server when
	setup server base on Windows 2008R2.
	19. RB-201205: NAS DNS-1250-04 and DNS-1550-04 remote
	replication failure
	20. RB-201224: iSCSI session is created between two NAS units,
	promise node name will appear
V03.00.4800.30 (Non-release version)	Remove all "Vendor's name and logo" on firmware and software
	1. RB-200925: Test E-mail alert shows no messages for the user if it is
V03.00.4800.31	successful or not 2. RB-201439: iSCSI connection between two NASes, iqn name is missing
(Non-release version)	 RB-201536: Dashboard shows the wrong icon highlighted RB-201524: Click on GUI, it sends the user back to login page. RB-201561: No need for firmware update reminder on GUI RB-201548: SNMP settings not saving after reboot.
	1. RB-200911: [PTT/Dlink] "Enable Power Management" in disk array settings could not checked
	2. RB-201523: [PTT/Dlink][Suggestion] Poor grammar – "is fails" It should be "This operation has failed"
V03.00.4800.32	3. RB-201528: [PTT/Dlink][suggestion] Poor grammar – "Move Successfull" when moving files on Web file manager
(Non-release version)	 RB-201939: [PTT/D-LINK] Smart log can not be enabled RB-201941: [PTT/Dlink] Email alert can't work on Hinet SMTP: msa.hinet.net
	 RB-201938: [PTT/Dlink] Remote backup can only "SYNC" RB-202066: [PTT/Dlink] Firmware can't be updated when the unit is
	on safe mode 8. RB-202059: [PTT/Dlink] When the GUI stays in "device", press F5 might go somewhere else
	1. RB-200911: "Enable Power Management" in disk array settings could
	not checked 2. RB-202059: When GUI stays in "device", press F5 might go somewhere
V03.00.4800.33	else
(Release version)	 RB-202450: the size for the file system is "-1" RB-202327: Enabling iscsi lun masking cause boot sequence error
	5. RB-202223: User "administrator" is unable to shutdown the device 6. RB-202189: Specific Delete DA steps will Crash
	7. RB-202189: Specific Delete DA steps will Crash 7. RB-202188: Enable Smart of Function description error

dlinkigreen



	8. RB-202186: WPPe_Physical Drive setting should be synchronized in front view
	9. RB-202185: WPPe_Offline function should remove in front view.
	1. RB-203323: there is no event for local backup
	2. RB-203320: manually run local backup will cancel the schedule
	3. RB-203317: migration had done, but ,file system extention doesn't
	 really work. 4. RB-202932: No information for device/iscsi/port about iscsi connection information 5. RB-203048: iTune server 10 doesn't seem to work with NAS
	6. RB-202580: when iSCSI connection got disconnect, it actually got
	deleted
	7. RB-203246: When the user is added to the second group, the user in the
V03.01.4800.01	original group will disappear
	8. RB-203428:iSCSI backup status shift a row
	9. RB-202914: default folder permission after letting NAS unit join AD
	10. RB-203074: "Create ISO folder" can't browse through image file and it
	can not work properly
	11. RB-203049: file is not found after factory default restore for DSN1550
	12.RB-202211: Target enable uni-direction CHAP authentication, then the
	other NAS can't connect by iscsi initiator
	13. RB-203028: EVT: Fans and LED settings cause Malfunction
	14. RB-203004: EVT:Icon problem of media center

Known Issues:

Firmware Version	Known Issues
V03.00.4800.28	N/A
V03.00.4800.33	N/A
V03.01.4800.01	N/A

Related Documentation:

N/A