



COVR-2600R (COVR-3902) Firmware Hotfix Release Notes

Firmware: 1.01B05_BETA01_Hotfix
Hardware Revision: Ax (Router Only)
Date: April 12, 2021

3rd Party Report:

Xiang Li <x-l19@mails dot tsinghua dot edu dot cn>
Network and Information Security Laboratory
Tsinghua University

Problem Resolved:

- DoS vulnerability results from IPv6 forwarding loops

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.