

## **DAP-1620 Firmware Release Notes**

Firmware: FW v1.05B05 Hardware: Rev. Ax Data:2017/02/15

## **Problem Resolved:**

- LED will now blink until it is connected to your router after WPS process finishes.
- Fix EDGE browser compatibility issue.