

DAP-1650 Firmware Release Notes

Firmware: 1.04B02 J65H Hot Fix

Hardware: Ax Date: June 6, 2019

Note:

Upgrade using the *DAP1650A1_FW104WWb02_j65h_middle.bin* file first, then upgrade with *DAP1650A1_FW104WWb02_j65h.bin*.

Report:

Vulnerabilities were discovered during independent research conducted by Aon's Cyber Labs (cyberlabs at aon doc com).

Problems Resolved:

- 1. Application Authentication Bypass via Forceful Browsing
- 2. Arbitrary Command Execution
- 3. WPA2 (KRACK)

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.