



## **DAP-2660 Firmware Patch Notes**

**Firmware: 1.15RC131\_B36**

**Hardware: Ax**

**Date: January 7, 2019**

### **Problems Resolved:**

1. Fixed issue when using Client and AP mode at the same time.
-