



Firmware Version: V1.01.07
Prom Code Version:
Published Date: 2015/3/26

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	2
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01.07	2015/3/26	DCS-2136L	A1
V1.00.13	2014/5/26	DCS-2136L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.01.07	<ul style="list-style-type: none">1. Change agent to v2.0.19-b022. Disable the SSL2.0/3.03. Disable the RC4/DES4. Add New DDNS Function (Select "Input Dynamic DNS Server" item)5. Support motion & privacy mask on non-IE browser6. Add 50MB/30 sec event for SD recording
V1.00.13	1 st version

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.07	<ul style="list-style-type: none">1. Remove the PSIA protocol. Fix getting the snapshot without authentication.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A