



Firmware Version: V2.13
Prom Code Version:
Published Date: 2015/10/12

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.00	2011/7/19	DCS-3710	B1
V2.10	2013/6/13	DCS-3710	B1
V2.11	2015/1/13	DCS-3710	B1
V2.12	2015/9/22	DCS-3710	B1
V2.13	2015/10/12	DCS-3710	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
4. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V2.10.01	1. Add SNMP function

Problems Fixed:

Firmware Version	Problems Fixed
V2.10.01	1. Remove the "guest" account. 2. RTSP Authentication change to default enable 3. Fixed the UPNP security issue.
V2.11.00	1. Fixed the security of SSL 3.0. 2. Fixed the security of getting the snapshot without authentication
V2.12.02	1.Fixed the security issue of NTPd issue 2.Fixed the security issue of tunneling RTSP streaming over HTTP 3.Fixed the Cross-Site Scripting(XSS) issue 4.Fixed the Cross-Site Request Forgery (CSFR) issue
V2.13.00	1. Upgrade to new signing keys for fixing Code-Signing Key issue

Known Issues:

Firmware Version	Known Issues
	N/A

Related Documentation:

N/A