



Firmware Version: V1.04

Prom Code Version:

Published Date: 2015/10/12

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.01.01	2013/05/13	DCS-6513	A1
V1.02.00	2015/01/07	DCS-6513	A1
V1.03.07	2015/10/12	DCS-6513	A1
V1.04.00	2015/10/12	DCS-6513	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

- 1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
- 2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
- 3. Click Browse... and specify the firmware file.
- 4. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.01	1. Add the SNMP Function.
	2. Change RTSP authentication default setting to "enable".
	3. Fixed SD card recording image unstable problem.
	4. Fixed lens out of focus after camera reboot problem.
V1.02.00	1. Fixed the security of SSL 3.0.
V1.02.00	2. Fixed the security of getting the snapshot without authentication
	Fixed the security issue of NTPd issue
V1.03.07	2. Fixed the security issue of tunneling RTSP streaming over HTTP
V1.03.07	Fixed the Cross-Site Scripting(XSS) issue
	4. Fixed theCross-Site Request Forgery (CSFR) issue
V1.04.00	Upgrade to new signing keys for fixing Code-Signing Key issue





DCS-6513 A1 Firmware Release Notes

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A

