



**Firmware Version:** V1.01  
**Prom Code Version:**  
**Published Date:** 2015/10/15

---

**Content:**

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: ..... 2

Known Issues: ..... 2

Related Documentation: ..... 3

## Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2015/9/7	DCS-6517	A1
V1.00	2015/10/15	DCS-6517	A1

## Upgrading Instructions:

Please follow normal business camera FW upgrade procedure.

## New Features:

Fireware Version	New Features
V1.00	First release

## Problems Fixed:

Firmware Version	Problems Fixed
V1.00	N/A
V1.01	Change new digital signature 2015

## Known Issues:

Firmware Version	Known Issues
V1.00	<ol style="list-style-type: none"> <li>1. Camera would reboot unexpectedly after remove the SD card during SD card recording is processing. The workaround solution is, do not remove SD card when the recording is writing. The issue will be fixed in next FW version.</li> <li>2. When camera upload configured file, the schedule recording setting of SD card is not proceed normal. The workaround solution is, reboot the camera to recover. The issue will be fixed in next FW version.</li> </ol>

**Related Documentation:**

---

N/A