



DCS-6517 Firmware Patch Notes

Firmware: 2.00.03 BETA9

Hardware: Bx

Date: November 26, 2018

Problems Resolved:

1. API "GetProfiles" get wrong H264 Profile return value.
 2. Fixed wrong format via /audio/ACAS-ULAW.cgi, /audio/ACAS-ULAW.cgi
 3. Fixed incorrect HW version display of ONVIF and NIPCA protocol
 4. Fixed AWB issue. (Using ONVIF test tool)
 5. Fixed E-mailing periodic snapshots not working. (DI20180111000001)
 6. Implement D-Link NIPCA DCS Authentication and Password encryption V1.2
-