



Firmware Version: V1.12
Prom Code Version: N/A
Published Date: 2015/10/12

Content:

Upgrading Instructions:.....	2
New Features:.....	2
Problems Fixed:	2
Known Issues:	Error! Bookmark not defined.
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2012/10/25	DCS-7513	A1
V1.01	2013/06/13	DCS-7513	A1
V1.10	2015/01/05	DCS-7513	A1
V1.11	2015/09/18	DCS-7513	A1
V1.12	2015/10/12	DCS-7513	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
4. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V1.01.03	1. Add SNMP function

Problems Fixed:

Firmware Version	Problems Fixed
V1.01.03	<ol style="list-style-type: none"> 1. Remove the "guest" account. 2. RTSP Authentication change to default enable 3. Fixed the UPNP security issue.
V1.10.00	<ol style="list-style-type: none"> 1. Fixed the security of SSL 3.0. 2. Fixed the security of getting the snapshot without authentication
V1.11.11	<ol style="list-style-type: none"> 1.Fixed the security issue of NTPd issue 2.Fixed the security issue of tunneling RTSP streaming over HTTP 3.Fixed the Cross-Site Scripting(XSS) issue 4.Fixed theCross-Site Request Forgery (CSFR) issue 5.Image improvement
V1.12.00	<ol style="list-style-type: none"> 1. Upgrade to new signing keys for fixing Code-Signing Key issue

Firmware Version	Known Issues
	N/A

Related Documentation:

N/A