



Firmware Version: V1.06_b4
Prom Code Version:
Published Date: 2013/2/20

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
v1.06_b4	2013/2/20	DCS-932L	A1
v1.05_b5	2012/11/19	DCS-932L	A1
v1.04_b5	2012/9/3	DCS-932L	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Firmware Version	New Features
V1.06_b4	<p>Firmware V1.06_b4 is only supported by wizard v1.02.10 or above.</p> <ol style="list-style-type: none">1. Change maximum admin password length, from 8 characters to 30 characters.2. Change PPPoE retry timing, retry connection on 30 seconds interval till connect.3. New ActiveX to support long admin password.4. Default time change to 2013-01-015. Change IR LED Night to Day switch timing to 7 seconds.
V1.05_b5	<ol style="list-style-type: none">1. Add mydlink agent version displayed on Web UI.2. Update Java program to support new mjpeg streaming format3. Change NTP request timing
v1.04_b5	<ol style="list-style-type: none">1. Upgrade new mydlink agent to v2.0.16-b42. Secure the configuration file with the new changed encryption method.3. Remove two WebGUI Hidden Pages for RD develop using.4. Remove the Telnet Daemon will be activated about 5 seconds when the Device is booting.5. Remove the hidden FTP server.

Problems Fixed:

Firmware Version	Problems Fixed

V1.05_b5	<ol style="list-style-type: none">1. Fixed ios6 live view hang issue – modify mjpeg streaming format2. Fixed sometimes startup java view failed on Win 7 + IE93. Fixed live view issue if http port is changed to 12345.4. Fixed live view streaming cannot pass through router's virtual server.5. Fixed e-mail loss issue when live view the camera.
v1.04_b5	<ol style="list-style-type: none">1. Fixed the live stream can't display when using the https connection.2. Fixed bad audio streaming on 3G internet access.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A