



DGS-1210-Series Firmware Release Notes

Firmware: 3.12B061 BETA

Hardware: Bx

Date: January 30, 2019

Problems Resolved:

1. If asymmetric vlan is enabled, packets sent by smart binding white list entry cannot pass through.(DI20180521000007)
-