

## **DIR-1960 Firmware Release Notes**

**Firmware: v1.02B01**

**Hardware: A1**

**Date: August 16, 2019**

### **Problems Resolved:**

1. Fixed Speedtest issue in some region
2. Fixed IPTV issue in some specific region/environment

### **Enhancements:**

1. Improved user experience for Wi-Fi Mesh
  2. Support DFS channel but DFS disable as default for IN country code
  3. Support EU VLAN
  4. AU/EU country code's Wi-Fi Mesh default value is changed from disable to enable (new default value will be effect after factory default for the Wi-Fi Mesh ON by default change.)
  5. IPv6 default value is changed from link local to auto detection. (new default value will be effect after factory default)
  6. Improved stability
  7. Improved VPN to create new account
  8. improved DFS behavior when mesh is paired
- 
-