

## DIR-615 Firmware Release Notes

**Firmware: FW805B046**

**Hardware: Hx**

**Date: 2013/08/21**

**Note:**

1. FW version is advanced to v8.05B04

**Problems Resolved:**

1. Fixed the multiple security vulnerabilities.
  - Solved the security issue in PPPoE account setting.
  - Solved the security issue in administrator setting
  - Solved the security issue for Ping function.
  - Solved the issue that firmware upgrade cannot work, which is caused by FW805B01 (only FW8.05 has this FW upgrading issue)
  - Solved the issue that ACL function can not work properly.
  - Solved the issue that PPTP connection will cause device crash when DHCP lease time arrives.
2. Fixed the multiple security vulnerabilities
  - Command Injection (tools\_vct.htm)
  - Cross Site Scripting (adv\_filters\_url.htm)
  - Cross Site Scripting (adv\_ipv6\_pppoe.htm)
  - Cross Site Scripting (tools\_ddns.htm)
  - Cross Site Scripting (tools\_email.htm)
3. Fixed the issue that when logging in with Chrome or Firefox browser in Linux system, it will be failed to access into management page.
4. Fixed the issue that when logging in with Chrome or IE browser in Windows system, it will be failed to access into management page.
5. Fixed the issue that sometimes the changed settings can't be applied in the system via Firefox browser.

**Enhancements:**

None