



DIR-815 Firmware Release Notes

Firmware: FW v2.01

Hardware: Rev. B1

Date: 2012/07/24

Note:

- FW can not be backward compatible with A1 version.

Problems Resolved:

- Fixed WLAN 5G MAC information issue in hidden page.
- DS-lite does not connect automatically when user change IPv6 settings.
- Add simple security option in IPv6 Firewall setting.
- Fixed wrong status in wireless mode when STA connect to DUT with 802.11a.

Enhancements:

None

Known Issues:

None
