



DIR-822 Firmware Release Notes

Firmware: FW v3.01.B02_WW

Hardware: REV. C1

Date: 2016/04/27

Note:

None

Problems Resolved:

- Fixed Security Vulnerability:
Stack-based buffer overflow exploit CVE-2016-5681 VU#332115 – Reported by Daniel Romero - NCC Group - Street: Calle Serrano Galvache Number: 56 Building: Abedul Floor: 4th, Madrid, 28033

For additional details please visit:

<http://supportannouncement.us.dlink.com/announcement/publication.aspx?name=SAP10063>

Enhancements:

- Enhanced Wireless Performance in high-Interference environments

Known Issues:

None
