



DIR-842 Firmware Release Notes

Firmware: v3.10B05

Hardware: Rev. Cx

Date: July 20, 2018

Note:

- The firmware version is advanced to v3.10B05.
- You must install firmware version 3.02B03 first, and then 3.10B05.

Problem Resolved:

- Fix translation issue.

Enhancements:

- Firmware protection.
- Update dnsmasq to 2.78.

----- END -----
