



DIR-842 Firmware Release Notes

Firmware: 3.13B09 Hotfix

Hardware: Cx

Date: December 23, 2019

Problems Resolved:

- CVE-2019-18852 - Hard-coded telnet credentials

3rd Party Report Information:

- <https://nvd.nist.gov/vuln/detail/CVE-2019-18852>

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.