

DIR-878 Firmware Hotfix Release Notes

Firmware: v1.30B08 Hotfix 04

Hardware: A1 Date: 10-13-2022

3rd Party Report:

The following report has been submitted from:

黄培扬 payoung at situ dot edu dot cn

Problems Resolved:

Addressed the HNAP command injection security issue

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an "as is" and "as available" basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.