



DIR-880L Firmware Release Notes

Firmware: FW v1.07.B08_WW (Release)

Hardware: REV. A1

Date: 2016/03/17

Note:

None

Problems Resolved:

1. Fixed Security Vulnerability:
Stack-based buffer overflow exploit - CVE-2016-5681 VU#332115 – Reported by Daniel Romero - NCC Group - Street: Calle Serrano Galvache Number: 56 Building: Abedul Floor: 4th, Madrid, 28033

For additional details please visit:

<http://supportannouncement.us.dlink.com/announcement/publication.aspx?name=SAP10063>

Enhancements:

1. Support basic VLAN tagging on WAN (Internet Port) for special Internet access
2. using Static IP, DHCP or PPPoE
3. Improved wireless multicast
4. Improved Edge browser compatibility
5. Supports MAC cloning for PPPoE configuration
6. Support Schedule Reboot
7. Adds HT20/40 Coexistence options for 2.4GHz wireless on management UI
8. Extends the number of rules from 15 to 24. (Static Route IPv4 and v6, Port Forwarding, Firewall IPv4 and v6, Virtual Server, Website Filter)
9. Parental control in Connected Client page can now be manually assigned to unconnected clients

Known Issues:

None
