



## DIR-882 Firmware Hotfix Release Notes

**Firmware:** v1.30.B06 Hotfix

**Hardware:** Ax

**Date:** June 28, 2022

**3rd Party Report:** 彭佳谦 <pengjiaqian@iie.ac.cn>

wanghuizhao@iie.ac.cn

### Problems Resolved:

1. Multiple Command Injection / Command Execution /

---

DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.